ILLINOIS TOOL WORKS

AA [illegible]
18T [illegible]AR
8DP 20°PA

THESE CHARTS SHOW THE TYPES OF WEAVE PRODUCED BY VARIOUS CONDITIONS OF RUNOUT AND THE AMOUNT OF ERROR EACH TYPE PRODUCES IN A GEAR TOOTH

E[illegible]ABISH
N[illegible]6, 1958